


Diplomat Dental s.r.o ., Vrbovská cesta 17, 921 01 Piešťany, Slovak Republic			
 DIPLOMAT DENTAL SOLUTIONS	Change description : revision of FARO_ADAPTER module	Change is valid for: Model One / Model Pro	Technical information No.: 023
		Change is valid from: 26/11/2024	Revision:

Revision of FARO_ADAPTER module

Dear valued customer, we would like to draw your attention to the latest revision of our FARO_ADAPTER module.

We are constantly trying to improve our customer experience and therefore, due to some previous complications with some lights from the manufacturer FARO changing the light intensity without an input from the dentist, we decided to make some changes to our FARO_ADAPTER module used in FARO MAIA lights, to prevent any potential malfunctions in the future.

The revision consists of a change to the input voltage, to our FARO_ADAPTER processing unit.

To make it easier for you to distinguish the original version from the revised one, in case you encounter such a problem with FARO MAIA, there is a **4.5V** label located on the revised module, which is easily noticeable next to the power input connection of the PCB.

The new revision of this module eliminates any potential problems with FARO lights changing the light intensity on their own, after prolonged usage.

If you have any further questions regarding this technical information or any other topic, please submit a ticket through our official **ticket.diplomat-service.com** website.

Thank you,

Diplomat Dental Solutions Team.