

 DIPLOMAT DENTAL SOLUTIONS	Diplomat Dental s.r.o., Vrbovská cesta 17, 921 01 Piešťany, Slovak Republic		
	Change description:	Change is valid for: Model One / Model Pro	Technical information No.: 028
	New Xenos Sensor	Change is valid from: 1/5/2025	Revision:

New Xenos Sensor

Dear Valued customer, we would like to inform you of a new change in our Diplomat Dental Solutions units.

Specifically, a new sensor module for the **Xenos** dental light on units Model Pro and Model One.

For Model Pro- new assembly item number: A653-900-008-0 – XENOS LIGHT MODEL PRO – includes the new sensor **Xenos N7_PREM (Only for Model Pro) - ME374000.525**

For Model One- new assembly item number: A653-900-006-0 – XENOS LIGHT MODEL ONE – includes the new sensor **Xenos N7 (Only for Model One) - ME374000.524**

The new modules are **not compatible with existing XENOS lights produced before this change** as the sensor has a different parts construction.

Previous modules **Xenos N6v0** - ME374000.429 and entire XENOS Lights with this older module on Model One and Pro will only be sold as **Spare Parts** and will be eventually phased out.

Reason for this change is future unforeseen unavailability of the **Xenos N6v0 – ME374000.429**.

If you have any questions regarding this technical information or any other topic, please submit a ticket through our official **ticket.diplomat-service.com** website.

Thank you,

Diplomat Dental Solutions Team.